

REPLACEMENT OF MAGNETOS

1 During overhaul of the Pratt & Whitney R985 Series engine, all Bosch SB9RU3 and SB9RC3 type magnetos are to be replaced by Scintilla type SB9RN magneto.

2 Bosch magnetos becoming unserviceable

in the field are to be replaced with magnetos of a similar type.

3 All unserviceable Bosch SB9RU3 and SB9RC3 type magnetos are to be reported to this command for disposal instructions.

ISSUED ON AUTHORITY OF THE CHIEF OF THE AIR STAFF

Prepared By:
AMC/SAESO/E1